G. R. S. 59] G.P.S—15,000—20-12-13

GENERAL AND REVENUE SECRETARIAT.

1895-96
~~191~~.
(Madurai)

File No. 11

Serial Nos.

Papers Filed.

Month

SUBJECT.

Repairs to the Sri Varadarajaswamy Temple at Maddur.

PREVIOUS REFERENCES LATER REFERENCES

G. O. Serial No 30.

1895

MUZARAL

From

To The Comptroller

Dated 29th May 1895

Despatched

Received

Endorsement No. /

G. O. (P. W.) No. 1056

~~Memo. No.~~

Sanctioning an estimate for Rs 865/ for repairing the Varadarajaswamy temple at Madolur

anne No 1097 dt 8-6-95
865
11-95 dt 10-9-95

No: 1056 dt 29/31/5/95 Eng

Which has been prepared after a ~~personal~~ visit thereto of the Temple by the Municipal ~~Inspection Committee~~

Order

The accompanying estimate for Rs 865 to repair the Sri Vanadarajaswami Temple in Madura, Nandya Taluk, is sanctioned, the charge being met from the State Grant of Rs 15000 sanctioned in Govt Order no. 996 Mun. J. 105-92 dt 24th March 1894, for the repairs of Muzarai Institutions in the Province during the year 1894-5

2. The amount ~~referred to~~ sanctioned in the foregoing para will be paid on

Gen. Serial No. 30.]

189

MUZARAI.

Presentation
to the Comptroller
of a bill Dd
Signed by the Inv.
Supt

From The Secretary to the Dewan of Mysor

To

Dated

Despatched

Received

Enclosures No.

General No.
Muzarai F. No.

To
The Comptroller
Dept

M.G.C.P.B.—21- 6-94 -

Gen. 50]

MUZRAI.

189

From

The Secretary to the

Government of Mysore.

To

The Comptroller to the Government of Mysore

Dated 8th

Despatched 8th June 1895.

Received

Enclosure / *No.* 2 &c.

General No. 1097
Muzrai F. No.

Govt. Pro: No. 1056 dated 29th May 1895, sanctioning an Estimate for Rs 865/- for repairing the Sri Varada-rajaswami temple at Maddur, in the Mandy Taluk.

With reference to the above, has the honor to forward herewith a bill for Rs 381-15-6 being the actual cost of work done ~~up to date~~ 25th May 1895 to the aforesaid

temple and to request that the same may be audited and returned to this office copy of the measurement list on which the bill is based is also herewith forwarded.

By order

[signature]

Secretary.

MH

Report to accompany
the measurement of work
done in Varada Raja-
Swamy temple at Mad

The dismantling and removi
of the outer stone wall and the inner
Brick wall is complete. The front door
which was not in good order has been
set right., and all the other works are
in good progress. Your honour was
pleased to order at Madduru that
the payment may be made once
in 15 days for the items of work that
are complete, and I got the Mutcha
written accordingly by the contractor
But again your ordered me that
the payment can only be made
when the whole work is complete

beg to bring to your notice that it was not only too late but also the contractor says that it is very difficult to complete the work within the proper time if he is not paid as per the conditions of the Mulchalika Bill yet I have made him to consent to get only one bill paid now and the rest to be paid when the whole work of each temple is complete In all there will be only 3 bills namely 2 for Varada Raja Swami temple and one for Narasimha Swami temple So the accompanying bill is the only one to be paid as a special case I have included in this bill only 3 works that are complete and this forms the full item of dismantling and Renewing. The Estimate for these 3 works was 396 Rupees but the measurement comes to only Rupees 381-15-6. so there

is a saving of Rupees 14-0-6 out of the orginal estimate. I beg you will be kind enough to pass orders for payment of the accompanying bill so that the work may be completed well and in time

I beg to remain
Sir
Your most obedient Servant
Balakrishna Rao

1st June 95
Maddur

The contractors name is Ammappa & is doing the work but yet I have mentioned Rangappa's name as the former is not rich and working with Rungappa's money and both of these are bachelors

B.R.

N. V. Venkatarao Narayana

P. V. [illegible]

P. V. [illegible]

Measurement of work done in Varada Raja Swami temple at Madden

Details		No	Dimension			Content	Total
Dismantling & Removing the outer Stone walls							
	Sides	2	39	1	12	.936	
	Rear	1	26	1	12	312	
	Front Sides	2	8	1	12	192	
	Front top	1	9	1	3	27	
	Total					1467	
Deduction for openings		1	20	1	6	120	
	Total c/ft						1341
Brick and Earthwork	Sides	2	38	4½	12	4104	
	Rear	1	15½	4½	12	837	
	Front Sides	2	3½	3½	12	294	
	Total c/ft						5235
Repairing the front Stone pillars of the Door sight —— Lump Sum Rate ——							50

Abstract

Quantity	Description of work	per	Rate	Cost Rs	as	p
1347	Dismantling Stone work	c/ft	- 2 -	168	6	-
5235	— Do — Brick & Earthwork	c/ft	- - 6	163	9	6
	Repairing the front Stone Pillars & the Door in good order ——	Lumpsum		50		
	Total			381	15	6

25th May 95
Madden

Balakrishna Rao
overseer

Form A.]

The Government of Mysore ..... Dr.

Particulars	Amount		Remarks
To			
The amount of actual cost of work done up to ~~date~~ 25th May 1895 to the Varadarajaswamy temple at Maddur in Mandya Taluk Mysore Dt	381	15-6	The amount to be met from the State Grant of Rs 15000/- sanctioned for the repair of Mouzam Institutes in the Province during the year 1894-95 vide Govt Pro: No 1056 dated 29th May 1895.
Rupees three hundred and eighty one, annas fifteen and pies six only			
To be made payable at the State Huzur (Fees Rs 1-7-9)	381	15-6	

Bangalore
June 1895

for Mouzam Sahere

R

No. 383 / M 711-95 dt 10-9-95

Ex. 3.

Read

Govt. Pro: No. 1056 dated 29th May 1895 sanctioning an estimate amounting to Rs. 865 for repairing the Sree Varadaraja Swami temple at Maddur in the Mandya Taluk.

Order thereon —

In the aforesaid estimate provision was not made for the execution of the marginally noted works. The Mudrai Superintendent during his late inspection carefully found that these works were urgently called for and gave personal instructions for their immediate execution. Accordingly they were carried out at a cost of Rs. 189-6-9

2. Under the foregoing circumstances the Govt.

	Cost Rs-As-Ps.
Dismantling the old Gopuram & Navaranga which were in a dilapidated condition	100-0-0
Cutting steps and stone benches	15-0-0
Constructing parapet over the main temple	4-14-0
Erecting compound wall with brick in mud	20-3-0
Sreenam plastering for the said well	12-11-6
Fixing water spouts for the main temple	6-0-0
Whitewashing and carrying out other petty repairs	15-10-0
Excess in brick work in the new temple	15-0-3
	189-6-9

Govt. are pleased to sanction the payment of the excess outlay of Rs. 189-6-9 from the sources specified below:-

A sum of Rs. 685/- was sanctioned in Govt. Pro: No. 1052 dated 29th May 95 to repair the Narsimhaswami temple at Madras from the State grant of Rs. 15000/- sanctioned for 1895-96. The actual cost incurred in repairing this temple amounted to Rs. 611-6-9 only and the balance of Rs. 73-9-3 is left as savings to be utilized for the repairs of the Varadaraja Swami temple at the same place	Rs. A. P. 73-9-3
From the State grant of Rs 15000/- sanctd. in Govt. Pro: No. 749 M.F. 105-92 dated 25th Feby. 95 for the repairs of Muzrai institutions in the Province for 1895-96.	115-13-6
Total	189-6-9

3. All the urgent repairs of the Varadaraja Swami temple at Maddur have been completed. The amount originally sanctioned to repair this temple from the State grant for 1894-95 in the Govt. Pro: cited above, is Rs. 865/. The excess or additional cost now sanctioned hereby is Rs. 189-6-9, that is the whole cost incurred in repairing the temple amounted to Rs. 1054-6-9 of which a sum of Rs. 381-15-6 has already been drawn on a separate bill (vide Mudgal Secy's Docket No. 1097 dated 8th June/95 to the Comptroller) and paid to the contractor and the balance to be still paid to him is Rs. 672-7-3. A bill for this amount is prepared and forwarded herewith to the Comptroller for

for audit and return
to the Mysore Govt
for payment.

4. A copy of abstract
of measurement and
completion report on
which the bill is based
will also be forwarded
to the Comptroller.

Secretary
to G.V.

To The Comptroller to the
Govt of Mysore with
the bill and copy of
abstract of measurement
& completion report.

Abstract of Measurement Book for *Varada Raja Swami temple, Attada*

Sub-Heads.	Previous Measurements				Present.						Total up to date.			
	Qy.	Cost.			Qy.	Rate.			Cost.		Qy.	Cost.		
Dismantling Stone wall	1347	168	6								1347	168	6	
Do - Brick & Earth work	5235	163	9	6							5235	163	9	6
Keeping the gate in good order.	LS 50	50									LS	50		
Brick in Chunam					1886	-	2		230	12	1886	230	12	
Roofing with Concrete					594	20			108	12	594	108	12	9
Chunam plastering					12.50	3			37	8	12.50	37	8	
Parapet					26		3		4	14	26	4	14	
Teak wood Door					60½	2			121		60½	121		
Cutting stone benches and steps					LS	15			15		LS	15		
Dismantling the old Goparum and Navarangam					L.S				100		LS.	100		

W .101]

Division

Sub-Division

Name of Work *Alterations to the Parade Steps, Lewisham at steeple Newydd*

Name of Contractor

Date of Measurement

Date of payment

Memo of Payments

(To be filled in Office of Payments)

Arrears brought forward

Work done as per this Bill

Total

Payment now made

Balance due

| | | |

Completion Report on the repairs executed
Varadarajaswami
the temple at Madura under the authority
of the Government. Proceedings No. 1056 Dated
29th May 1895. Muzrai Department

cription of work	Es as	Amt more	Differences less	Remarks.
ismantling and moving Stone walls	150	168 6.	18 6	The Stones were hidden in earth so the excess was effected
ismantling and moving the Brick d Earth work.	198	163 96	34 6 6	
etting the front-gate in good order.	50. -	50.		
eak wood door for e gate	132 . .	121	11	
rick in chunam.				
ls for the main uilding (outside)	12 . .	230½	102-12	This excess is due to the [illegible] for [illegible]

[illegible]

Description of work	Estimated amount	Amt. as executed	Differences more	Differences less	Remarks.
Roofing with Concrete ~~for the roof~~	135 . .	108 12 9		26 3 3	The rate was cut down as the Jelly was supplied by Government.
Chunam plastering for the main walls ~~for the roof~~	27 . .	37 8 .	10 8		
Parapet	.	4 14	4 14 .		~~New work~~
Putting Stone ~~the~~ Steps and benches in the Compound ~~to the Compound~~	.	15 . .	15 . .		~~Do~~
Dismantling the old Goharam ~~and the~~ ~~old~~ dilapidated ~~Compound~~	.	100	100		
Brick in mud for Compound wall .	.	20 3	20 3 .		
Chunam plastering for Compound wall	.	12 11 6	12 11 6		
Water Shoots	.	6 . .	6 . .		
White washing	.	5 10 .	5 10 .		2nd time done
Petty Repairs for the floor of Gurbagudi and Silt clearing	.	10 .	10 . .		

~~Yours~~ are new items of work done as per Overseer Subordinate's orders as they were not provided for in the original estimate.

Balakrishna Rao
Overseer
Chunnai Department

N° 583 8-->

Name of work

Repairing the Varada Raja Swami temple at Maddur

Authority for work

Govt Pro No 1056 Dated 29th May 1895

Amount of Estimate

865

Expenditure

1054-6-9

The Government of Mysore

Particulars	ount	Remarks-
The amount of actual cost ~~all the repairs~~ works done ~~in the~~ 26th May ~~1893~~ 1889 to the Varada Raja Swamie temple at Maddur, Taluk, Mysore District.	672 7 3	The amount to be met as ~~stated~~ below:—
		Rs ~~479-10-9~~ 483-11-6 from the balance of the State Grant of Rs 15000/- sanctioned for 1894-95 and ordered to be credited to the Muzrai Surplus Funds Vide Govt Pro. No. 16 dtd 9/06-92 dated 9th July 1895.
		73-9-3 from the savings effected out of Rs 685 sanctioned for repairing the Narasimha Swami temple at Maddur.
		Rs ~~115-13-6~~ 115-13-6 from the State Grant of Rs 15000/ sanctioned for 1896-96
Rupees Six hundred and ~~two~~ one, annas seven and pies three only.		
To be made payable at the State Huzur Treasury)	672 7 3	672- 7- 3 Total

Vide Govt Pro. No. 383 Mis. dated 18th Sept 95

~~Rs 1000/- 957~~ gallons.

Rs 381-13-6 vide Muzrai Receipt No 09 dtd 8th June 96.

read

Govt Pro: No 1056 dated 29th May 1895 sanctioning an estimate amounting to Rs. 865 for repairing the Shree Varadaraja Swami temple at Maddur in the Mandya Taluk.

-Do- -do- No 383 M.R. 11-95 dated 10th Septr 1895 sanctioning the payment of an excess outlay of Rs. 189-6-9 on account of certain additional works executed to the aforesaid temple.

No. 936 / M7 11.95 dt 25/2/96
Encl

Order thereon —

The Mudgal Subsidy who inspected the temple lately found that the execution of some other additional works was absolutely necessary and consequently ordered the preparation of a supplemental estimate

The Subhalamma

estimate prepared by the overseer, Mudgrai Dept^t for Rs. 160/ to carry out ~~these~~ these additional works to the Varadaraja Swami temple at Maddur is sanctioned the charge being met from the State grant of Rs 15000/ sanctioned in Govt^t Order No. 749 M.F. 103-92 dated 25th July/95 for the repairs of Mudgrai institutions in the Province for the year 1895-96.

3 The amount of Rs. 160/ sanctioned in para 2 above will be paid on presentation to the Comptroller of a bill duly signed by the Mudgrai Dept^t.

Mudgrai Secretary
C.V.

To The Comptroller, Mysore
Govt^t with a copy of the
Superintt^s abstract estimate

Supplemental.

Estimate of the probable cost of Repairing the Varada Raya Swami temple at Alladdu

Concrete for the Basement floor						
Sides	2	40	3	-	240	
Rear	1	20	3	-	60	
Total						300
Compound wall (Brick in mud)	1	50	1½	4	250	
Total						250
Chunam plastering	1	50	9	-	450	
Total						450
White washing (two coats)						300
Pointing with Chunam for Gusba Gudi new Slabs & old Slabs &c					L.	200
Flooring the Gusba Gudi	1	1	15	-	225	
Total						225
1 Big lock. Wooden folding Stairs in the Gus Gudi to make puja to the God -					Rs	25
Earth work & Site-clearing					Rs	20

Abstract

	Per	Rate		₹	cost
Concrete for the Basement	S	8	..	3·00	24
Brick in mud	Cft	-	2	250	31
Chunam plastering	Sqr	3	4	4·50	14
White washing (2 coats)	Sqr	—	4	30·00	7
Pointing Gurba floor	Sqr	1	.	2000	20
Flooring with Slabs (using old ones)	Sqr	5	.	2·25	11
Fitting wooden Shutters				1	25
Earth work & Site clearing				L.S.	20
Total					152
Contingencies at 5%					8
Grand Total Rupees					160